

# Lessons Learnt from the DOMS Mooring Parting Accident

## 5<sup>th</sup> UK Moorings Workshop

Mario Brito<sup>1</sup> and Mark Hartman<sup>2</sup>

<sup>1</sup>Underwater Systems Laboratory

<sup>2</sup>Ocean Biogeochemistry and Ecosystems

Contact: [{mch,mpb2o07}@noc.soton.ac.uk](mailto:{mch,mpb2o07}@noc.soton.ac.uk)






*Location of the PAP mooring deployed in June 2007. RV Celtic Explorer, cruise CE716. Courtesy of Google Earth.*



# PAP1 mooring parted

PAP1 DOMS  
AS DEPLOYED 2007  
CELTIC EXPLORER



A new multidisciplinary mooring DOMS (Deep Ocean Monitoring Station) was deployed at the PAP time series observatory in June 2007.



The mooring had a design specification duration of 18 months.


Various features failed and the mooring ultimately parted 47 days after deployment.

The top part of the mooring was recovered by R/V Pelagia in September 2007.

An investigation was conducted to investigate the root cause of the accident.

Lampitt, R., Brito, M.P., Campbell, J., Comben, D., Edwards, T., Griffiths, G., Hartman, M., Hartman, S., Larkin, K., Pagnani, M., Pebody, C. and Waddington, I. (2008) Reliability Case Notes No. 2. PAP 2007: DOMS mooring loss report. National Oceanography Centre Southampton Research and Consultancy Report, 51, 43pp.









*Surface buoy position with watch circles (Mercator).*





# Event Tree




Level	N	Failure Mode	Likelihoods
5	4	Line tangled with sb and high sea state	43.6%
4	3	Inappropriate material for the shackle seizing	36.1%
6	5	High sea state e.g. days 206-8	16.5%
3	2	Shackle not seized	1.37%
3	6	Material failure	0.94%
4	7	Line tangled with sb and high sea state	0.68%
2	1	Shackle vandalised	0.55%
4	8	High sea state e.g. days 206-8	0.12%
4	9	Fishing gear	0.14%
<b>Total</b>			<b>100%</b>

*Failure modes identified using the fault tree analysis. Three experts assessed all evidence collected from the investigation.*

Design fault was considered to be the root cause for the parting of the mooring.


Bad seizing of the shackle may also have contributed to the accident

## Upon recovery...



- On 2<sup>nd</sup> October 2008 all of the expected mooring was recovered except for a single top 17" sphere, 750m of nylon rope and a 100kg weight.
- The upper 1500m rope section of the mooring had been cut.
- Long line fishing gear (hooks and line) entangled were found entangled with the rope.
- The rope had been stopped off several times and there was antifouling paint along lengths of the rope.

# Event Tree



Level	N	Failure Mode	Likelihoods
1	1	Rope cut and shackle undone	51.7%
3	2	Bottom shackle failed- shackle vandalized	20.4%
4	3	Bottom shackle failed - shackle pin becomes loose - inappropriate material	5.67%
5	4	Bottom shackle failed - shackle pin becomes loose – line tangled with sb and hss	6.84%
2	5	Rope cut – tangled and parted	4.33%
3	6	Rope cut – human	3.97%
5	7	Bottom shackle failed - shackle pin becomes loose – high sea state e.g. days 206-8	2.59%
3	8	Rope cut – propeller	1.7%
3	9	Bottom shackle failed - shackle breaks – material failure	1.28%
4	10	Bottom shackle failed - shackle breaks – line tangled with sb and hss	0.93%
3	11	Bottom shackle failed- shackle pin becomes loose - shackle not seized	0.21%
4	12	Bottom shackle failed - shackle breaks – fishing gear	0.19%
4	13	Bottom shackle failed - shackle breaks – high sea state e.g. days 206-8	0.16%
<b>Total</b>			<b>100%</b>

***Failure modes. Fishing activity is deemed the top reason for the parting of the top side of the mooring.***



# Implementation of learnt lessons

- 1: Change design so there is no floating horizontal line to tangle with the surface float.
- 2: Incorporate restraints on shackles to reduce damage at junctions.
- 3: Put an AIS proximity sensor on the surface buoy which will automatically transmit the identity of a nearby vessel.
- 4: Surround mooring with guard buoys.
- 5: Install proximity activated camera on surface buoy with satellite transmission.
- 6: Acoustic warning of approaching ship.
- 7: Develop communication with tuna fishermen (possibly through ICCAT) both to encourage them to avoid the area and to design more durable moorings.
- 8: Advise location on all charts and in fishermen's magazines.

