

„ROV PHOCA“ is limping a bit...

Dr. Friedrich Abegg

During the Factory Acceptance Tests a strange behaviour of the vehicle while using station keep or auto altitude has been detected.

After several trials in natural environment like harbour basins and open water a visit of a SubAtlantic technician recently revealed that the control software does not process the data from the DVL

Actually SUBATLANTIC is working on that problem and we hope to receive a software update until mid of January.

Nevertheless ROV PHOCA is in an operable state with only some ,comfort' restrictions to the pilots 😊

Best regards to all OFEG TECH participants and hope to be able to participate again next year.

Fritz Abegg–ROV Team Kiel